



Department of Transportation

ANDREW M. CUOMO
Governor

MATTHEW J. DRISCOLL
Commissioner

Cathy Calhoun
Chief of Staff

May 15, 2017

OPERATOR ID 2404

ONONDAGA COACH CORP.
ROUTE 34 NORTH STREET ROAD
AUBURN NY 13021

Dear Motor Carrier:

Enclosed is the annual New York State Department of Transportation Bus Inspection System Operator Profile that summarizes the results of vehicle inspections performed on your fleet by the Department during the last State Fiscal Year (April 1, 2016 to March 31, 2017). For regular inspections, the profile identifies the number and percentage of vehicles that passed or were placed Out-of-Service (OOS) due to one or more OOS defects. It is the Department's continued goal to have all operators pass at least 90% of their scheduled safety inspections. The current statewide average OOS rate is 5.2%.

We would like to congratulate those operators who have achieved the goal of a 90% or greater pass rate. Your commendable performance indicates a strong dedication to safety and a commitment to sound maintenance standards and practices.

Operators who have a passing rate of less than 90%, it is requested that your organization examine the enclosed profile inspection data and immediately update your maintenance program in order to achieve the Department's stated goal. Your Regional Bus Inspection Program Supervisor is available to review the actions being taken and provide assistance, if necessary to address any needed changes.

For those operators whose OOS rate is 25% or greater and fall under the Department's enforcement program, you will be contacted shortly to address your unacceptable poor performance. Actions may include civil penalties, unannounced vehicle inspections, denial of B & C privileges, compliance reviews or other regulatory enforcement.

Please visit <https://www.dot.ny.gov/divisions/operating/osss/bus> for program updates.

Sincerely,

Lawrence Scotto, Acting Director
Passenger Carrier Safety Bureau

Enclosures

cc: Regional Bus Program Supervisor